

Concept Plan

Council will be undertaking minor works at Cole Reserve, Pascoe Vale this financial year. We will advise of works timing when known.



Upgrades will include:

- Replacement seating where existing seats are in poor condition.
- A circular path around the passive recreation area of Cole Reserve. This will be a combination of gravel path with a concrete path. We will also provide connecting concrete paths.
- Replacing existing drinking fountains with new accessible units, adjacent to paths.
- Replacement post and rail fencing by the car park.
- We will also assess drainage to see what improvements can be made in the reserve.

Key:

Backed seat with arms




Platform seat



Accessible drinking fountain



Concrete path



Aggregate path

